


guides and given a new Part No. 33079. Stocks of the original parts will be maintained for the servicing of engines prior to Engine No. EL/CC/33079 as the two assemblies are not interchangeable. The tappet clearance remains at .006 for both inlet and exhaust valves.

Please refer to Spares Note 76, for parts change information.



Item No.94. REAR ROOF LIGHT - VANS ONLY

From Engine No. ED/CC/29995 an additional Roof Light has been fitted over the rear door way on Bradford Vans. The new roof light operates in conjunction with the forward roof light.

For Parts Information, please refer to Spares Note 66.