

## Item No.28 CONNECTING RODS - P.B. MODELS.

From engine no. EO/PB/10506 a new type connecting rod (Part No. 54024) has been incorporated in the Javelin engine.

It should be noted that the mating faces of the connecting rod and the connecting rod cap are serrated to ensure a more accurate re-assembly of these parts after dismantling.

When fitting the new type connecting rod to engines previous to no. EO/PB/10506 or when replacing cylinder liners in engines fitted with the new type connecting rods, it is most IMPORTANT to check the clearance between the connecting rod and the skirt of the cylinder liner. The liner cut out maybe modified, if necessary as detailed in the sketch below.

Please refer to Spares Note No.51 for Parts Change information.

